out to Clyde. If you have this schematic, please return it or a signed receipt to me. If you do not have it, please indicate any knowledge you may have concerning this.

The following accounts are still carried on the books at the local field site:

\$16.25 FOIAb3a 6.25 12.50

It was discovered that the input tubes in the B unit monitor amplifiers were specially selected for proper operation. This was not a proper solution to the problem. If the cathode resistor in the first stage is raised from 1000 ohms to 1600 ohms, the input tubes should not require special selection.

The 1-kc crystal oscillator does not operate in some units because of improper bias on the transistor oscillator stage. In some units the resistor from collector to 28 volts is 30,000 ohms. This should be changed to 10,000 ohms. This will improve the stability and starting characteristics of the oscillator.

The heated covers for the B unit are accessory items. For this reason, the plastic covers should not be returned to the factory.

As the field supervisor, FOIAb3a can submit expenses for car rental if this transportation is required to perform his duties and if he can justify this expense to the extent that we can be reimbursed by the customer.

as returned to the ZI on emergency leave. FOIAb3a leaving on November 15th as a permanent replacement. leaves on the FOIAb3a 19th for the second location.

FOIAb3a

FOIAb3a FOIAb3a Three field engineers have accepted positions with us. They are These men will probably be working with Systems 1 and 3.

It is important that your weekly reports be continued. In these reports include anything that should be added to the manuals and any revisions that 25X1A should be made to the manuals.

PWA:hcp Prolembroved For Release 2000/09/01 : CIA-RDP81B00878R000200050108-1 statement Insurance Brochure Memo 8/29/56

3 cys. memo 11/2/56 re: Travel Expenses and Income Tax